How to Use a CMM Machine: A Foundational Guide

This document explains how to use a CMM machine to measure and verify the geometric features of manufactured parts. A Coordinate Measuring Machine (CMM) is a device used to measure and report geometric features of manufactured parts, including circles, lines, squares, and geometric dimensioning and tolerancing (GD&T) parameters such as angularity and circularity. Understanding how a CMM operates, the coordinate systems it uses, and where it is applied will help you interpret CMM output correctly and recognize why it is preferred over conventional metrology methods.

Purpose

The purpose of this procedure is to provide a foundational understanding of what a Coordinate Measuring Machine is, how it captures and processes measurement data, and how its results are used to confirm that a manufactured part matches its intended design and functional purpose.

Scope

This guide applies to anyone who needs to understand the operating principles of a CMM before working with one, including personnel in aerospace, automotive, healthcare, pharmaceutical, and food processing environments where CMMs are used for quality control and inspection.

Required equipment

- Coordinate Measuring Machine (CMM) with a probe
- Connected computer system running CMM software
- Manufactured part to be measured
- Engineering drawing with reference dimensions for comparison
- Protective clothing, where required by the facility's hygiene standards (common in food processing, pharmaceutical, and healthcare settings)

Step-by-step procedure

Step 1: Identify the CMM and its function

Locate the CMM unit and confirm it consists of a probe and a connected computer system. The CMM's role is to measure and report geometric data from the part under inspection.



A 3D rendered image of a CMM with a probe, computer monitor, and the text "Coordinate Measuring Machine (CMM) - A Device to Measure and Report"

Step 2: Identify the geometric features to be measured

Before measuring, identify which geometric features on the part need verification, such as lines, circles, squares, circularity, and angularity. The quality of a manufactured part depends on how closely these features match the intended design.



A 3D model of a part with highlighted and labeled features: Line, Circularity, Circle, Square, and Angularity

Step 3: Compare the part to its engineering drawing

Reference the engineering drawing alongside the physical part. The CMM's measurements will be compared against these design specifications to confirm the part meets its functional requirements.



An engineering drawing with front, top, and side views, dimensions, and a 3D model of a part labeled "BLOCK"

Step 4: Establish the coordinate system relative to the part

Confirm the origin point (0, 0, 0) on the part and understand how points are defined by three values (X, Y, Z) relative to that origin in three-dimensional space.



A 3D part with overlaid X, Y, and Z axes, origin marked as (0, 0, 0), and a highlighted point at (10, 1, 2)

Step 5: Perform probing

Move the CMM's probe along the X, Y, and Z axes so it contacts the part at specific locations. This process of collecting point coordinates is called probing.



A probe touching a corner of a yellow cube, with X, Y, and Z axes labeled and the contact points circled

Step 6: Review the software's feature tracing

Allow the CMM software to convert the coordinates obtained from probing into geometric features using mathematical formulas. The software traces characteristics such as length, width, angle, and diameter by connecting the measured points.



A 3D grid with X, Y, Z axes, points labeled with coordinates such as (0, 3, 3), and lines connecting the points to form a geometric shape

Step 7: Review feature relationships

Use the software to establish relationships between two or more features by measuring the distance and angle between them. Confirm calculated values for length, width, angle, and diameter, and verify that corner angles match the expected 90° specification where applicable.



A diagram showing a square with a circle inside, labeled with Length, Width, Angle, and Diameter, with all corners marked as 90°

Step 8: Understand the Cartesian coordinate system

Recognize that the CMM can measure using the Cartesian coordinate system, which defines a point by its distance from the origin along the X, Y, and Z axes.



A diagram showing the Cartesian coordinate system with labeled X, Y, and Z axes, origin, and a cube outlined in dashed lines, titled "Cartesian Coordinate System"

Step 9: Understand the cylindrical coordinate system

Recognize that a point can also be defined using the cylindrical coordinate system, based on the radial distance (r) from the origin, the angle (θ) made with the horizontal axis, and the distance along the Z-axis.



A diagram showing the cylindrical coordinate system with X, Y, Z axes, origin, radial distance r, angle θ, and a vertical line for the Z component, titled "Cylindrical Coordinate System"

Step 10: Understand the spherical coordinate system

Recognize that a point can also be defined using the spherical coordinate system, based on the radial distance (r), the angle (θ) made with the vertical axis, and the angle (φ) made with the horizontal axis. The CMM can convert coordinates between the Cartesian, cylindrical, and spherical systems, providing flexibility in measurement and analysis.



A diagram showing the spherical coordinate system with X, Y, Z axes, origin, radial distance r, angle θ, angle φ, and overlaid dashed circles, titled "Spherical Coordinate System"

Step 11: Compare CMM measurement to conventional metrology

Note that conventional metrology requires different instruments, such as calipers, micrometers, and dial gauges, for different measurements, which makes the process tedious and error-prone. A CMM provides a flexible process with a single device.



A split image comparing Conventional Metrology, with calipers, a micrometer, and a dial gauge labeled "Tedious and Error-Prone Results", against a CMM machine and computer labeled "Flexible Process and Reliable Results"

Step 12: Compare repeatability

Note that conventional metrology is less repeatable, while CMM measurements are repeatable and highly accurate due to their automated, software-driven process.



A split image comparing Conventional Metrology, labeled "Less Repeatable", against a CMM labeled "Repeatable and Highly Accurate"

Step 13: Verify accuracy ranges

Confirm the expected accuracy for your equipment. A typical 1-meter bridge-type CMM offers an accuracy range of 2 microns to 5 microns (0.000078 in. to 0.000196 in.), compared to 25 microns to 50 microns for conventional metrology.



A split image comparing Conventional Metrology, labeled "Less Repeatable", against a CMM labeled "Repeatable and Highly Accurate" with an accuracy of 2 µm to 5 µm (0.000078 in. to 0.000196 in.)

Step 14: Observe the industrial application environment

Note that CMMs are used across industries including aerospace, automotive, healthcare, pharmaceuticals, and food processing, where they provide precise, repeatable measurements and automate quality control. In such environments, a conveyor system, automated packaging machinery, and a digital control panel displaying measurement data (for example, "290.3 g") support automated weighing or inspection. Personnel should wear protective clothing where the environment requires adherence to hygiene standards, as is critical in healthcare, pharmaceutical, and food industries.



A modern industrial production line with a conveyor system, digital control panel displaying measurement data, automated packaging machinery, and personnel in protective clothing

Step 15: Confirm integration with automated inspection systems

Verify that the CMM is integrated into the production line to perform real-time measurements and inspections. This integration helps ensure product consistency, compliance with standards, and efficient throughput. In industries like food processing and pharmaceuticals, this verifies product dimensions, weights, and packaging integrity; in aerospace and automotive, it ensures components meet strict tolerances for safety and performance.



A close-up of the conveyor and control panel, highlighting the integration of automated measurement and inspection systems in an industrial setting

Verification and summary

After completing these steps, you should be able to confirm the following:

- The CMM has probed the part and captured accurate X, Y, Z coordinate data.
- The software has correctly traced geometric features and calculated relationships such as length, width, angle, and diameter.
- The measured part matches the specifications on its engineering drawing.
- The coordinate system used (Cartesian, cylindrical, or spherical) is appropriate for the measurement task, with conversion available between systems as needed.
- The measurement results fall within the expected accuracy range for the CMM equipment used.

- Where applicable, the CMM is properly integrated into the automated production and inspection workflow, and hygiene or protective clothing requirements have been followed.

By completing this procedure, you will have a working understanding of how to use a CMM machine to measure geometric features, apply the correct coordinate system, and confirm that a manufactured part meets its design and functional requirements with greater flexibility, repeatability, and accuracy than conventional metrology methods.